MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT: **AUTOMATIC TRANSMISSION HYDRAULIC CIRCUIT — SERVICE MANUAL CORRECTION**

NO. TSB-91-23-006
DATE February, 1991
MODEL 1987-90 Van/Wagon, 1990 Montero

TSB Revision TSB-91-23-006

PURPOSE

This bulletin corrects a hydraulic circuit callout in the automatic transmission section of affected models. As a reference to this bulletin, place the TSB Revision number in the box at the bottom of the affected Service Manual pages.

AFFECTED SERVICE MANUALS

1987 Van/Wagon, Volume 1, Page 21-30
1988 Van/Wagon, Volume 1, Page 21-30
1989 Van/Wagon, Volume 1, Page 21-6
1990 Van/Wagon, Volume 1, Page 23-6
1990 Montero, Volume 1, Page 23-6

DETAILS OF CORRECTION

(Change affected pages as indicated below)



* * * * * * This circuit contains line pressure. Shade it with a red-colored pencil or pen to match the other line pressure circuits.

023783

FILE UNDER: Group 23 Automatic Trans. in the Dealer Service Information Binder (872)

CIRCULATE TO:
- ☐ GENERAL MANAGER
- ☐ PARTS MANAGER
- ☑ TECHNICIAN
- ☐ SERVICE ADVISOR
- ☑ SERVICE MANAGER
- ☐ WARRANTY PROCESSOR
- ☐ SALES MANAGER